

Certificate of Conformity

Certificate No: 38573 **Date Inspected:** 20/09/2024
Date Of Issue: 21/07/2025 **Engineer:** Daisy
Next Inspection due: 20/09/2025

**Where applicable, Results are traceable to National Standards via UKAS Certified
Collimator System No. 2082**

Fleet No: SG/044 **Description:** Radiodetection Genny4
Serial No: 10/G4EN-30371

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN
ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....

JB Survey Ltd is an ISO9001:2015 registered company No. FS30408