

Certificate of Conformity

Certificate No: 39626

Date Inspected: 23/01/2025

Date Of Issue: 13/08/2025

Engineer: Daisy

Next Inspection due: 23/01/2026

**Where applicable, Results are traceable to National Standards via UKAS Certified
Collimator System No. 2082**

Fleet No: PL/001

Description: Leica Piper 100 Pipe Laser

Serial No: P100-08295

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN
ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....

JB Survey Ltd is an ISO9001:2015 registered company No. FS30408