

Certificate of Conformity

Certificate No: 40582 Date Inspected: 24/04/2025
Date Of Issue: 24/04/2025 Engineer: Daisy
Next Inspection due: 24/04/2026

Where applicable, Results are traceable to National Standards via UKAS Certified
Collimator System No. 2082

Fleet No: PL/020 Description: Leica Piper 100 Pipe Laser
Serial No: P100-09846

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN
ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....*Daisy Loughran*.....