

Certificate of Conformity

Certificate No: 42537

Date Inspected: 22/12/2025

Date Of Issue: 22/12/2025

Engineer: Daisy

Next Inspection due: 22/12/2026

**Where applicable, Results are traceable to National Standards via UKAS Certified
Collimator System No. 2082**

Fleet No: PL/054

Description: Leica Piper 100 Pipe Laser

Serial No: 2441P230227

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN
ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....*Daisy Loughran*.....

JB Survey Ltd is an ISO9001:2015 registered company No. FS30408