

Certificate of Conformity

Certificate No: 42943 **Date Inspected:** 10/02/2026
Date Of Issue: 10/02/2026 **Engineer:** Daisy
Next Inspection due: 10/02/2027

Where applicable, Results are traceable to National Standards via UKAS Certified Collimator System No. 2082

Fleet No: PL/056 **Description:** Leica Piper 100 Pipe Laser
Serial No: P100-11123

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....*Daisy Loughran*.....